WELLS LAMONT Industrial	PRODU	CT SPECIFI	CATION SHEET	WHI ARD.
	PR		ORMATION	
Style:	1878			Second Carl
Sizing:	Size Part #		Overedge Clor	and the second
	Small Medium Large XLarge	1878S 1878M 1878L 1878L	Yellow Blue White Orange	
Registered Brand Name: Classification:	Whizard® Cut Resistan	t		
	PR	ODUCT DES	SCRIPTION	
Description: Color: Material: Gauge:	Metalguard® Medium Weight Yellow / Gray High Performance Fibers and Stainless Steel 10			
Sold by: Packaging (Inner Pack): Packaging (Case Pack):	Pair 3 Pairs 60 Pairs			
CU	F PROTECTIO	ON PERFOR		ATION
Test Method: Test Results:	ASTM F1790-97 2574 grams / 5.67lbs. ANSI Level 4			
Test Method: Test Results:	ASTM F2992 2580 grams ANSI Level A	-		
ABRAS			FORMANCE INFO	RMATION
Test Method: Test Results:	ASTM D3884 ANSI Level 2			
	WA	SHING INST	RUCTIONS	
Remove all large particles. Rins minutes. Water temperature sh 150°F (67°C). Do not use blead	ould not exceed 16	60ºF (71ºC). Rinse		detergent or soap for 10-15 / for 10-15 minutes, not exceedin
		CAUTI	ON	
Gloves are cut resistant but are not	t cut or puncture-proo	f. Do not subject to	high-speed, serrated blades	or intentional slashings.
	Toll-Free 1.	Wells Lamont I	ndustrial wellslamontindustrial.com	