WELLS LAMONT

Industrial

PRODUCT SPECIFICATION SHEET

WHI ARD.

PRODUCT INFORMATION

Style: VS 13

<u>Size</u> <u>Part #</u> <u>Overedge</u>

Sizing:
White

 XSmall
 135027
 Green

 Small
 135028
 Yellow

 Medium
 135029
 Blue

 Large
 135030
 White

 XLarge
 135031
 Orange

Registered Brand Name: Whizard®
Classification: Cut Resistant

PRODUCT DESCRIPTION

Description:Wireless Cut Resistant GloveColor:Available in White or Gray

Material: High Performance Fibers; Wireless

CFR 21 - Approved for Food Contact

Latex Free

Packaging (Inner Pack): 6 Pieces
Packaging (Case Pack): 120 Pieces

CUT PROTECTION PERFORMANCE INFORMATION

Test Method: ASTM F1790-97 **Test Results:** 1541 grams / 3.40lbs.

ANSI Level 4

Test Method: ASTM F2992-15
Test Results: 1006 grams

ANSI Level A3

ABRASION PROTECTION PERFORMANCE INFORMATION

Test Method: ASTM D3884-09

Test Results: ANSI Level 2, 700 Cycles

WASHING INSTRUCTIONS

Remove all large particles. Rinse with cold water then machine wash in warm water with mild detergent or soap for 10-15 minutes. Water temperature should not exceed 160°F (71°C). Rinse in cold water. Tumble dry for 10-15 minutes, not exceeding 150°F (67°C). A diluted bleach solution may be used (5.25% sodium hypochlorite or 1:10 household bleach).

CAUTION

Gloves are cut resistant but are not cut or puncture-proof. Do not subject to high-speed, serrated blades or intentional slashings.

Wells Lamont Industrial

Toll-Free 1.800.247.3295 www.wellslamontindustrial.com

© 2019 Wells Lamont Industrial, LLC - All rights reserved.

KM 04/19